

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 07/25/2012	3. Time Prepared 1800
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Mindy Luetke, Planning Section Chief		6. Operational Period 1200, 07/19/12 – 1200, 07/26/12
7. Personnel Roster Assigned			
Name	ICS Position	Home Base	
Matthew Haak	Situation Unit Aerial Field Observer	Houston, TX	
8. Activity Log			
Time	Major Events		
0800	<p>Operational Observation:</p> <ul style="list-style-type: none"> • Morrow Lake Delta observed sheen sweep boat operating along Booms A-F. • Morrow Lake Delta observed the Agitation Effects Study. • Morrow Lake Delta when we were leaving the agitation affects study sheen and oil was observed when the boat reversed. • Morrow Lake north cove observed sheen sweep boat. • Morrow Lake south cove observed sheen and tar globs in a ~750' x 300' area. • Morrow Lake observed sheen sweep boat responding to sheen in the south cove. • MP36.25 observed sheen in the river channel. • MP36.0 LDB sheen observed • Morrow Lake poling crew observed near the E4 boat launch. • Morrow Lake Delta observed camera inspection of the curtain long Boom A. • Morrow Lake observed the quantification coring team. • Ceresco Dam observed sheen at the portage take out. No decontamination station was observed at the portage. • MP5.5 LDB observed sheen and tar globs. • MP5.63 Railroad trestles observed sheen and tar globs. • Ceresco Dam sheen sweep boat observed. • Ceresco Dam sheen observed. <p>Planning Activities:</p> <ul style="list-style-type: none"> • Completed 214 • Prepared and distributed Daily Situation Unit Photolog. • Continued preparation of weekly Situation Report "SitRep" • Continued updating Organizational Staffing Gannt Chart. • Assisted with the C&G and MAC Situational Update presentation. 		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit, USEPA-START			